General Environmental Incident Summary

Incident: 3437 Date/Time Notice: 8/1/2014 DEM Incident No:

Responsible Party: Magic City Oil

Date Incident:8/1/2014Time Incident:0867Duration:County:WardTwp:157Rng:83Sec:36Qtr:Lat:48.37389Long:-101.34280Method:Navigation quality GPS

Location Description: 12966-13032 30th Street Northwest, Minot, ND 58703, USA

From Ruthville, ND - 2 miles West and 1/4 mile north

Submitted By: Tiffanie Fettig Affiliation: Magic City Oil

Address: 1915 Highway 2 Bypass Eas

PO Box 105

City: Minot State: ND Zip: 58701

Received By:

Contact Person: Tiffanie Fettig

1915 Highway 2 Bypass East

PO Box 105 Minot, ND 58701

Distance Nearest Occupied Building: 0.13 Miles Release Contained: Yes

Type of Incident: Vehicle Accident

Description of Released Contaminant: 10 gallons of gasoline and 18.2 gallons of diesel fuel

Volume Spilled: 28.20 gallons Ag Related: No

EPA Extremely Hazardous Substance: Unknown Reported to NRC: Unknown

Cause of Incident:

Fuel truck was traveling down the road and pulled over to let another vehicle go by - when started again and no shoulder on the road front right tire went down to lower elevation and the weight in the truck shifted and truck rolled into the ditch.

Risk Evaluation:

no immediate health risks.

of Fatalities: 0 # of Injuries: 0 Affected Medium: 02 - water

Potential Environmental Impacts:

No likely environmental risks as spill was almost completely cleaned up within hours of the spill. A minimal amount of gallons was spilled.

Action Taken or Planned:

Rural Fire department responded and put out containment items around the truck even though there was no visable spill at the time. Once the truck was removed you could see some fluid floating on the surface of the water. Earthmovers was contacted to respond and they put out pads to collect all fluid. They pushed away a few cat tails to insure that all fluid was contained on the surface and soaked up by the pads.

Friday, January 27, 2017 Page 1 of 2

Wastes Disposal Location: Earthmovers will dispose of all collected waste.

Agencies Involved: Local Fire Department, Local Law Enforcement

Updates

Date: 8/24/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Volume:

Notes:

Release from fuel truck accident. Water filled ditch. Strata responded and cleaned up the released fuel. Followup with the company is necessary to determine reason for delay in reporting the release through the NDDoH online reporting system.

Date: 6/3/2015 Status: Inspection Author: Kangas, Kathleen

Updated Volume:

Notes:

Visited site 06/03/15. Cattails pushed aside in area of truck rollover, but new growth is showing. Redwing blackbirds seen around area. Some staining on edge of road at rollover site, but there is no smell of gas/diesel or oil. No sheen visible.

Friday, January 27, 2017 Page 2 of 2